

Mine Name: Topliff Quarry

Operator Name: Staker & Parsons Companies

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program September 01, 2009

Reviewed: My

Permit Number: S/045/00072

Inspection Date: July 09, 2009

Inspector(s): L Heppler	Time: 8:30 am Mine Status: Active		
Other Participants: none			
Elements of Inspection	Evaluated	Comment	Enforcemen
1. Permits, Revisions, Transfer, Bonds	\boxtimes	\boxtimes	
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Reclamation			
7 Backfilling/Grading (trenches nits roads highwalls shafts)			

Bond Renewal Date: 12-06-2010 Bond Amount: \$47,600 Permit fee is delinquent

Purpose of Inspection: Routine annual Inspection. This site has never been inspected as a small mine site.

Inspection Summary: Area disturbed is greater than 5 acres, bond amount is for 11.6 acres, but permit is for a small mine of 5 acres. Operator is working on a large mine permit for the site. Fence above the high wall needs to be repaired. The dominant species in the valleys are Indian ricegrass, winterfat, and sand dropseed; bluebunch wheatgrass on the slopes, and Sandberg bluegrass on the ridge tops. Every effort should be made to salvage top soil from the site prior to exploration or mining.

See attached photographs which were taken to document site conditions.

Conclusions and Recommendations: OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:vs

8. Soils9. Revegetation

cc: Mike Dalley

 $O: \label{lem:condition} O: \label{lem:condi$



